# A Tool for Simulating Rotating Coil Magnetometers

L. Bottura, M. Buzio, P. Schnizer, N. Smirnov

2. October 2001

#### Introduction

- Series magnet measurement systems at CERN are mainly based on the rotating coil technique.
- Magnets are extremely large and measurement requirements are demanding.
- The aim is to identify the weak spot in the measurement system and to improve the measurement quality of the system.
- The calculation is based on first principles.
- The description of imperfections is kept as simple as possible.

## Contents

- 1. Basic Formulae
- 2. Mathematical Approaches
- 3. Physical Models
- 4. Implementation
- 5. Validation
- 6. Example Applications

## **Measurement of Field Components**

Magnetic Field B(z):

$$B(z) = B_y + iB_x = \sum_{n=1}^{\infty} \left[ B_n + iA_n \right] \left( \frac{z}{R_{Ref}} \right)^n$$

$$B_n + A_n \cdot i = C_n \dots \text{multipoles}$$

 $R_{Ref}$  ... reference radius

Flux  $\Phi$  seen by a coil:

$$\Phi(t) = \sum_{n=1}^{M} K_n C_n \cos [n\beta(t)].$$

 $\beta(t)$ ...angular position of the coil

The sensitivities  $K_n$ :

$$K_n = \left(\frac{N_w L R_{Ref}}{n}\right) \left[ \left(\frac{z_2}{R_{Ref}}\right)^n - \left(\frac{z_1}{R_{Ref}}\right)^n \right]$$

 $N_w$  ... number of windings

 $z_2$ ,  $z_1$ ... the inner and outer radii respectively of the coil

L ... Length of the Coil

Voltage V(t) induced into the coils:

$$V(t) = -n \dot{\beta}(t) \sum_{n=1}^{N} K_n C_n \sin \left[ n\beta(t) \right].$$

The harmonics are given as:

$$C_n = \frac{1}{K_n} FT \left( \int_0^P V(t) dt \right).$$

FT...Fourier Transform

P ... time of one rotation


## Mathematical Approaches

- In Fourier Space
- In Time Space purely numerical
- In Time Space semi numerical

## **Fourier Space**

- The magnetic field is described as Harmonics.
- The induced voltage could be described as a spectrum of n.
- Electronic Noise has a spectrum.
- Each component is effecting the spectrum of the previous one.
- An missing mark of the angular encoder, a drifting power supply is difficult to model.


#### Time Space purely numerical



Deviation of the coils movement from the ideal line

Follow the deviation from the ideal line and change the sensitivities accordingly. They must be differentiated numerically.

#### Time Space semi numerical



Coil imperfections are modelled by correcting the induced voltage for each time step using analytical formulae.

- The sensitivities  $K_n$  are well known but the formalisms are more complex.
- This was considered a sufficient advantage to accept the tradeoff of the more complicated formalism.
- The usage of the sensitvities allows the simple modelling of a bucked system.
- The frequency space approach was not considered further as some components are difficult to model.

## **Physical Models**

- First principles are used to describe each element and its imperfections.
- The description of the imperfection is kept as simple as possible.
- They still allow the input of experimental experience e.g. the torsional vibrations of mechanical connections are modelled using a series of decaying frequencies.

- motor
  - $ideal: \omega t$
  - imperfection:  $\sum_{i=1}^{N} A_i \sin (\alpha_i t + \phi_i)$
- mechanical connections
  - $ideal : \theta(t)$
  - imperfection:  $\sum_{i} e^{-d_i t} a_i sin(c_i t + \psi_i)$
- rotating coils:
  - ideal:

$$V(t) = -n \dot{\beta}(t) \sum_{n=1}^{N} K_n C_n \sin [n\beta(t)].$$

- *imperfection* : transversal vibrations

- the angular encoder:
  - *ideal* : triggers the measurement.
  - *imperfection* : Spurious marks. Sinusoidal errors
- cables:
  - *ideal* : transfer the signal from source to receiver.
  - *imperfection* : pickup of electromagnetic noise, thermal voltages
- *electronics:* compensation circuitry, preamplifier, integrator

- ideal: 
$$U_{OE} = \int_{t'_0}^{t'_0+P} G_P \sum_i G_{C_i} U_{IC_i} dt$$


- *imperfections:* Input - Output Offset voltages, non linear amplification.

### **Implementation**

- In a real system the behaviour and influence of each component is influenced by the attached devices and the surrounding environment.
- Software mirror → Object Oriented Hierarchy
- encapsulation of the key parameters
- 6 digits accuracy → possible using double precision
- integration using ODE solver

## Validation

- pure ideal case
- Transversally vibrating coil  $1\mu m$  equals measurement resolution 6 digits match analytically and numerically
- Torsionally vibrating coil



Example of the influence of a torsional vibrating coil on the measurement of the octupole in a pure quadrupole field for a vibration p=2.

## **Example of Applications**

Search for a fake harmonic in a dipole:

- Magnet Calculation gave a small quadrupole harmonic in a dipole.
- A far too large quadrupole was measured.
- Study, what measurement system imperfection and which quantity gives such an error.




Figure 1: Harmonics found in a LHC dipole prototype. The quadrupole harmonic is rather large.

### Noise coupled into the cable


Noise model:

$$U_N(t) = \sum_{i=1}^{N} q_i e^{-r_i(t-t_{0i})} \sin [s_i (t-t_{0i})].$$

 $q_i, r_i, s_i$ ... vibration parameters

 $t_{0i}$  ... start time of the peak

All parameters are set randomly.



Noise in the cable induced by the environmental pollution of a switching power supply.

Table 1: Influence of the electrical noise on the harmonics

voltage $q_{max}$ [mV]	0.1	1	10
$\boxed{[Cn/C2 \cdot 10^4]}$	$10^{-4}$	$10^{-3}$	$10^{-2}$
$C_2 = 1.5 T @ R_{Ref}$			
$Cn/C2 \cdot 10^4$	$7 \cdot 10^{-4}$	$7 \cdot 10^{-3}$	$7 \cdot 10^{-2}$
$C_2 = 0.2 T @ R_{Ref}$			

## Conclusion

- A tool available allowing the simple investigation of imperfections
- Allows the study of noise
- The modularity allows to add new components